CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	E. COLI	T. COLI	TEMP	pH
Feyrer Park Bridge	12/17/2008	<1	0.6	N/D	2.0	127.4	0.8	7.7
50ft Upstream Of Outfall	12/17/2008	<1	0.8	N/D	5.2	133.3	0.9	7.7
50ft Downstream Of Outfall	12/17/2008	<1	0.8	N/D	6.2	129.1	0.9	7.7
Highway 211 Bridge	12/17/2008	<1	0.8	N/D	6.3	142.1	1.0	7.7
IRRIGATION DITCH								
Feyrer Park Bridge At Irrigation Ditch	12/19/2008	<1	1.8	N/D	14.8	461.1	1.5	6.9
Pipe Crossing At Irrigation Ditch	12/19/2008	<1	1.8	N/D	5.2	648.8	1.3	6.9
N/D = Nondetectable								