CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	E. COLI	T. COLI	TEMP	pH
Feyrer Park Bridge	2/12/2009	<1	0.6	N/D	4.1	129.1	3.1	6.9
50ft Upstream Of Outfall	2/12/2009	<1	0.6	N/D	6.2	145.0	3.1	7.0
50ft Downstream Of Outfall	2/12/2009	<1	0.6	N/D	5.2	127.4	3.1	7.0
Highway 211 Bridge	2/12/2009	<1	0.8	N/D	4.1	142.1	3.3	7.0
IRRIGATION DITCH								
Feyrer Park Bridge At Irrigation Ditch	2/13/2009	<1	1.8	N/D	2.0	165.8	4.0	7.5
Pipe Crossing At Irrigation Ditch	2/13/2009	<1	1.2	0.2	12.0	285.1	4.2	7.3
N/D = Nondetectable								