CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	E. COLI	T. COLI	TEMP	pH
Feyrer Park Bridge	1/7/2009	<1	17.2	0.2	7.2	193.5	7.5	7.6
50ft Upstream Of Outfall	1/7/2009	<1	20.8	N/D	6.2	248.1	7.5	7.7
50ft Downstream Of Outfall	1/7/2009	<1	18.4	N/D	8.3	261.3	7.6	7.7
Highway 211 Bridge	1/7/2009	<1	24.8	0.1	4.1	248.1	7.7	7.5
IRRIGATION DITCH								
Feyrer Park Bridge At Irrigation Ditch	1/9/2009	<1	12.4	N/D	15.8	488.4	6.0	7.4
Pipe Crossing At Irrigation Ditch	1/9/2009	<1	15.8	0.3	33.6	980.4	5.9	7.4
N/D = Nondetectable								