CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	E. COLI	T. COLI	TEMP	pH
Feyrer Park Bridge	1/14/2009	<1	0.6	N/D	2.0	93.4	5.2	7.1
50ft Upstream Of Outfall	1/14/2009	<1	0.4	N/D	4.1	156.5	5.3	7.2
50ft Downstream Of Outfall	1/14/2009	1.0	2.0	N/D	5.1	155.3	5.3	7.2
Highway 211 Bridge	1/14/2009	1.3	1.6	N/D	17.3	344.8	5.5	7.4
IRRIGATION DITCH								
Feyrer Park Bridge At Irrigation Ditch	1/16/2009	<1	1.4	N/D	4.1	238.2	4.9	7.5
Pipe Crossing At Irrigation Ditch	1/16/2009	<1	8.8	N/D	4.0	275.5	4.8	7.5
N/D = Nondetectable								