CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	E. COLI	T. COLI	TEMP	pH
Feyrer Park Bridge	1/21/2009	<1	0.6	0.2	4.1	99.0	3.6	7.1
50ft Upstream Of Outfall	1/21/2009	<1	0.6	0.3	2.0	121.0	3.6	7.1
50ft Downstream Of Outfall	1/21/2009	<1	0.6	0.3	1.0	112.6	3.6	7.1
Highway 211 Bridge	1/21/2009	<1	1.0	N/D	2.0	148.3	3.8	7.2
IRRIGATION DITCH								
Feyrer Park Bridge At Irrigation Ditch	1/23/2009	<1	0.6	N/D	3.0	387.3	4.2	7.2
Pipe Crossing At Irrigation Ditch	1/23/2009	<1	1.6	N/D	5.1	344.8	4.6	7.0
N/D = Nondetectable								