CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	E. COLI	T. COLI	TEMP	pH
Feyrer Park Bridge	1/28/2009	<1	0.6	0.2	4.1	116.2	3.8	7.2
50ft Upstream Of Outfall	1/28/2009	<1	0.6	N/D	4.1	133.3	4.0	7.3
50ft Downstream Of Outfall	1/28/2009	<1	0.8	N/D	3.0	126.6	4.1	7.2
Highway 211 Bridge	1/28/2009	<1	0.8	N/D	6.3	119.8	4.1	7.2
IRRIGATION DITCH								
Feyrer Park Bridge At Irrigation Ditch	1/30/2009	<1	0.4	0.2	7.3	325.5	3.4	7.2
Pipe Crossing At Irrigation Ditch	1/30/2009	<1	1.4	0.4	5.1	365.4	3.4	7.0
N/D = Nondetectable								