CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

| **MOLALLA RIVER** | DATE | BOD | TSS | NH3 | E. COLI | T. COLI | TEMP | pH |
|---|---|---|---|---|---|---|---|---|
| Feyrer Park Bridge | 11/12/2008 | 1.0 | 14.8 | N/D | 36.8 | >2419.6 | 10.4 | 6.6 |
| 50ft Upstream Of Outfall | 11/12/2008 | <1 | 15.4 | N/D | 21.8 | >2419.6 | 10.4 | 6.4 |
| 50ft Downstream Of Outfall | 11/12/2008 | <1 | 16.0 | N/D | 20.3 | >2419.6 | 10.4 | 6.4 |
| Highway 211 Bridge | 11/12/2008 | 1.7 | 20.2 | 0.1 | 33.1 | >2419.6 | 10.5 | 6.4 |
| | | | | | | | | |
| **IRRIGATION DITCH** | | | | | | | | |
| Feyrer Park Bridge At Irrigation Ditch | 11/14/2008 | <1 | 6.2 | N/D | 64.4 | >2419.6 | 7.9 | 6.4 |
| Pipe Crossing At Irrigation Ditch | 11/14/2008 | <1 | 7.6 | N/D | 107.1 | >2419.6 | 7.8 | 6.4 |
| | | | | | | | | |
| **N/D = Nondetectable** | | | | | | | | |