CITY OF MOLALLA
WATER POLLUTION CONTROL FACILITY

WEEKLY GRAB SAMPLE RESULTS

MOLALLA RIVER	DATE	BOD	TSS	NH3	E. COLI	T. COLI	TEMP	pH
Feyrer Park Bridge	9/3/2008	<1	0.4	N/D	8.5	1732.9	13.4	6.9
50ft Upstream Of Outfall	9/3/2008	<1	0.4	N/D	18.9	1732.9	13.4	6.9
50ft Downstream Of Outfall	9/3/2008	<1	0.4	N/D	18.5	1553.1	13.5	7.0
Highway 211 Bridge	9/3/2008	<1	0.6	N/D	12.0	2419.6	13.8	7.0
IRRIGATION DITCH								
Feyrer Park Bridge At Irrigation Ditch	9/5/2008	1.04	2.0	N/D	31.5	1732.9	14.8	7.1
Pipe Crossing At Irrigation Ditch	9/5/2008	1.22	3.8	N/D	35.5	>2419.6	15.1	7.1
N/D = Nondetectable								